

New Build Check List

Note: We are not Connected to the Cape Royale Property Owners Association.

This is not an Offical Check List

	044 ADDDECC			
	911 ADDRESS			
	USUALLY GIVEN WITH PERMIT OR OFFICE OF EMERGENCY MANAGEMENT			
	Packet from POA			
	Phone Number: 936-653-3233			
	Office Address: 6 Sales Dr. Coldspring TX 77331			
Cape Royale Utility District				
	Step 1			
	fill out Initiation Form (online or at office)			
	(to get approval for POA's ACC meeting)			
	Turn in:			
	☐ Initiation Form			
	Survey			
	☐ Plot Plan			
	Before approval is given:			
	We'll determine if an encroachment is needed.			
	If an encroachment is needed you will come to the office.			
	We will fill out the encrochament and collect the \$35.00 fee and Signature. Then we file it at the court house.			
	Then we like it at the court house.			
These are reviewed on Tuesdays and turned into the POA ACC.				
Th	e Field Supervisor Mike Jacobs will call you upon completion.			
	Meeting w/ Cape Royale Property Owner's Association's Architectural Control Committee.			
Check List Continuned on back				



New Build Check List

Note: We are not Connected to the Cape Royale Property Owners Association.

This is not an Offical Check List

Cape Royale Utility District			
		Step 2	
	fill out [Orainage packet	
	make \$	500.00 Deposit	
		we'll determine culvert size	
	sta	ndard is 18" galvanized or preferred HDPE	
	Confirm	Next step for Depoosit Refund with office	
		Step 3	
Now when you need water you will come down and fill out a tap app			
	ŀ	nere at the office things you need to know:	
	-It gen	erally takes 6-8 weeks to tap.	
	-No co	ontious water without a CSI	
	Fill out	Tap App/ make deposit	
	it is \$1 0	0.00 security deposit w/ 5/8"meter \$1,600.00	
	5/8" me	eter Total \$1,700.00	
		*please dicuss other options with Field Supervisor	
		Tap will be installed	
		Meter will be locked off until csi is complete	
		CSI's will be done	
		Number of CSI's will variy for each build	
		Sewer Inspection will also be done	
		Please do not bury any sewer lines until inspection is done	